

Please remit payment to: 1432109 Ontario Ltd. O/A Zoom Rent-A-Car 5825 Dixie Rd, Mississauga, Tel #: 905-670-7368



"YOU MAKE THE CALL...

...ZOOM WILL BE THERE"

HST# 89802-0219 RT0001

Nov 19, 2019

Customer Name - Luiz Fernando

RA # 103930 Claim # 0006645713

BREAKDOWN OF CHARGES

Repairs as per estimate Downtime (4 days@69.99) Admin fee \$904.92 \$223.97 (80 % charged) \$100.00

TOTAL OUTSTANDING BALANCE:

\$1228.89

* Please remit the payment to zoom rent a car.

RALEIGH APPRAISAL SERVICE 38 SOUTH BALSAM

UXBRIDGE, ON L9P 1V4

TELEPHONE: (905) 852-5300 FAX: (905) 852-5310

*** PRELIMINARY ESTIMATE ***

18/11/2019 08:04 PM

Owner

Owner: Zoom Rent-A-Car Contact: Zoom Rent-A-Car

Address: 5835 Dixie Rd.

City Province Postal: Mississauga -, ON L4W 4V7

Email: claims@zoomrentals.com

Work/Day: (905)670-7368

FAX:

Control Information

Claim #: UNIT:SUV182 F

Loss Date/Time: 18/11/2019 05:00 PM

Deductible: None

File #:

Insured Policy #:

Loss Type: Collision

Accounting #: RA#103992

Ins. Company: RALEIGH APPRAISAL SERVICE

Address:

City Province Postal: Oshawa, ON

Email: Raleigh@powergate.ca

Claimant: Ali Mokhtar Sasani

Work/Day: (905)852-5300

FAX:

Inspection

Inspection Date: 18/11/2019 08:01 PM

Inspection Location: Zoom Rent-A-Car

Address: 5835 Dixie Rd.

City Province Postal: Mississauga -, ON L4W 4V7

Email: claims@zoomrentals.com

Primary Impact: Front

Inspection Type: Field

Contact: Zoom Rent-A-Car Work/Day: (905)670-7368x

FAX:

Company: Raleigh Appraisal Service

Contact: Fred Zabalet

Address:

Secondary Impact: Appraiser License #:

Work/Day: (905)852-5300

Email: raleigh@powergate.ca

Repairer

Target Complete Date/Time:

Days To Repair: 4

Remarks

****No supplements authorized without prior approval, parts invoices and old parts must be kept for inspection****

Vehicle

2019 Hyundai Tucson Preferred 4 DR Wagon

4cyl Gasoline 2.0 6-Speed Automatic

Lic.Plate: CJXL242

Lic Expire: Veh Insp#:

Condition: Excellent
Ext. Colour: WINTER WHITE
Ext. Refinish: Two-Stage
Ext. Paint Code: PDW,PKW

Lic Province: ON

VIN: Unreadable VIN

Kilometer Type: Actual

Code: E7224B

Int. Colour: Int. Refinish: Int. Trim Code:

Options

4-Wheel Drive 2nd Row Head Airbags 1st Row LCD Monitor(s) Aluminum/Alloy Wheels Air Conditioning AM/FM CD Player Armrest(s) Auto Emergency Braking Anti-Lock Brakes Blind Spot Sensor Auxiliary Audio Input Auto Locking Hubs (4WD) Center Console Color-Keyed Bumper(s) **Bucket Seats** Dual Airbags Cruise Control Cross Traffic Alert Electronic Transfer Case Electric Steering Elect. Stability Control Fog Lights Ext Mirror Turn Signals Floor Mats Heated Power Mirrors Head Airbags **Heated Front Seats** Heated Wiper Park Heated Rear Window Wiper Heated Steering Wheel Keyless Entry System Intermittent Wipers Illuminated Visor Mirror Lane Departure Alert LED Daytime Running Lts LED Brakelights Lighted Entry System Leather Steering Wheel Leather Shift Knob Overhead Console MP3 Decoder Limited Slp Differential Power Brakes Power Door Locks Perimeter Alarm System Pwr Accessory Outlet(s) Power Windows Projector Beam Headlamps Rear View Camera Rear Window Defroster Rear Lip Spoiler Side Airbags Rear Window Wiper/Washer Roof Rails Strg Wheel Radio Control Tilt & Telescopic Steer Tachometer Traction Control System Touch Screen Display Tinted Glass Velour/Cloth Seats Voice Activatd Cellphone Trip Computer Wireless Phone Connect

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
Front E					A stated			3.8	SM
	Ν	18		Frt Bumper Cvr Overhau	Additional Labour				SM
2	I	6		Cvr,Front Bumper Upr	Repair			2.0*	
3	L	6	13	Cvr,Front Bumper Upr	Refinish 2.4 Surface 0.6 Two-stage setup 0.5 Two-stage			3.5	RF
4	Ε	67		Filler, Front Bumper RT	86528D3500	\$9.05		INC	SM
5	Ε	445		Filler, Front Bumper RT	86526D3530	\$17.77		INC	SM
Radiato	or Su	port							
6		13		Calibrate, Frt End Came	Additional Labour			0.5*	ME
7	N	102		Calibrate, Cruise Cntl RT	Additional Labour			0.4*	ME
Manual Entries									
	SB	M03		Flex Additive	Sublet Repair	\$10.00*			RF
9	N	M15		Colour Tint	Additional Labour			0.5*	RF
=	SB	M60		Hazardous Waste Removal	Sublet Repair	\$5.00*			SM
11	N	M67		Reset Electrical Component	Additional Labour			0.8*	ME*

>> PPS.

11 Items

11 Items						
	MC	Message				
	13	INCLUDES 0.6 HOURS	FIRST PANEL	TWO-STAGE ALLO	DWANCE	
Estimate Total & Entrie	s					
Gross Parts Paint & Materials Shop Materials Parts & Material Total			\$30.00 \$3.00	\$26.82 \$120.00 \$22.50	\$169.32	
Labour	Rat	e Replace Repair Hrs Hrs	s Total Hrs			
Sheet Metal (SM) Mech/Elec (ME) Frame (FR) Refinish (RF)	\$60.0 \$78.0 \$60.0 \$60.0	0 1.7	7 1.7	\$348.00 \$132.60 \$240.00		
Labour Total Sublet Repairs Harmonized Sales Tax Gross Total Less: Deductible Net Total		@ 13.000%	11.5 H	ours \$15.00	\$720.60 \$117.64 \$1,022.56 None- \$1,022.56	

Alternate Parts No

SPPL Yes Postal Code: Default

Rate Name Default

Audatex Estimating 8.0.642 Update 6 ES 19/11/2019 09:32 AM REL 8.0.642 Update 6 DT 01/11/2019 DB 15/11/2019 © 2019 Audatex North America, Inc.

1.1 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS IS NOT AN AUTHORIZATION TO REPAIR. THIS IS AN APPRAISAL ONLY. RALEIGH APPRAISAL SERVICE ASSUMES NO RESPONSIBILITY FOR REPAIR, SAFETY AND QUALITY. ADDITIONAL REPAIRS REQUIRE REINSEPECTION.

Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labour	EP = Replace PXN	EU = QLTY RECYCLED PART
TE = Partial Replace Price	PM= Replace PXN Reman/Reblt	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labour
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipquard	RI = R & I Assembly	P = Check
oo ompgaara	ž	

19/11/2019 09:32 AM Page 3 of 4

AA = Appearance Allowance

RP = Related Prior Damage



Audatex

This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2019 Audatex North America, Inc. AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.



CHARGE #2

TO:

☐ CASH ☐ CHEQUE

60 CHARGE #1

21 RENTER'S SIGNATURE X



Inspection Sheet


Rental Agreement No.

Vehicle No. Licence No.

Make

SYMBOLS

- WIND-SHIELD
- LUGGAGE MARK
- **DENOTES DENT**
- **DENOTES SCRATCH**
- **DENOTES MISSING**
- SURFACE SCRATCHES



Rental customer is fully liable for all damage and or repairs if such damage is caused by a collision with any object because of insufficient clearance (height or width), the overloading of the rental vehicle, or the neglect and abuse of the rental vehicle. Any after hour returns or the vehicle is not returned to a rental original location in person, customer is responsible for all damage to vehicle until inspection by the rental staff. By signing this agreement you agree to our TERMS & CONDITIONS.

DAMAGE LOSS REPORT-ZOOM RENT A CAR			
RA Number: 103930	Claim Number:		
Date of loss:	Claim Number.		
VEHICLE			
	Plata Na. CTV10110		
Make, model, year: 2019	Plate No: CTX L242 YUNDAI TUCSON		
INSURED	9010VA) 1003010		
Name of the driver: LU12 FERNAN	100 10000100		
Contact: 647 878 019 4	I PO IMENES		
	APT401, TORONTO, ON M4POC		
OCCURENCE	THE TOTAL PORTION OF THE OPEN		
Location of occurence: I DON'T KNOW			
	NO THE VEHICLE, A PAINT		
	PORTED TO ME. 1 SIDNIT NOTICE		
	WASNIT INVOLUED IN ANY		
THIRD PARTY INFORMATION	COULD CAUSE THAT DAMGE.		
Was there a third party involved?	Yes No		
If yes, provide the details:	Phone		
Insurance	Policy		
POLICE REPORT	Folicy		
Was the accident reported to police?	Yes No		
Report number:	Yes No		
INJURIES/PROPERTY DAMAGE			
Occupants:			
Any body Injured in accident?	Yes No		
Name of the injured person:	res No		
Contact:	· · · · · · · · · · · · · · · · · · ·		
Address:			
Is there any damage to property?	Yes No		
INSURANCE			
Name of the Insurance Company:			
Policy number: Secondary insurance if			
any	Yes No		
Name:	Policy Number:		
	, 191		
Rental agent Signature: Tajirden Sigh	Renter Signature: Long talk his talk		
Date: 2019			